

**Warning:**




1. If sensor leaks request the SDS information from the factory.  
1a. *Si le capteur fuit, demandez les informations SDS à l'usine.*

**Installation instructions:**



1. For accurate initial calibration, allow sensor and device Electronics to equilibrate for 20 minutes after installation
2. Refer to your owner's manual for proper installation and calibration instructions.
3. DO NOT DROP: (Sensor can be permanently damaged).
4. DO NOT: (Open or apply pressure to either end of sensor).

**Warranty: FOB Factory**



**Manufacturer's Authorized European Representative:**  
**Distribuciones y Representaciones Biomedicas Direx, S.L.**  
**Address: Avda. San Pablo, 28. Nave 24, 2882 Coslada Madrid, Espana**