

BẢNG KÊ CHI TIẾT TRANG THIẾT BỊ Y TẾ

STT	Tên trang thiết bị y tế	Chủng loại sản phẩm	Hãng, nước sản xuất	Hãng, nước chủ sở hữu	Tên cơ sở bảo hành	Địa chỉ cơ sở bảo hành
1	Mũi cắt răng giả	TC Cutter (0110.023HP, 0210.023HP, 0310.023HP, 0410.023HP, 0610.023HP, 0710.023HP, 0810.023HP, 0910.016HP, 0910.023HP, 1010.023HP, 1110.023HP, 1210.016HP, 1310.008HP, 1310.009HP, 1310.010HP, 1510.014HP, 1610.014HP, 1710.023HP, 1810.023HP, 3510.012HP, 5110.006HP, 5210.060HP, 5310.060HP, 5410.060HP, 5510.060HP, 5610.045HP, 5710.040HP, 5810.060HP, 5910.060HP, 6110.040HP, 6210.040HP, 6310.060HP, 6410.031HP, 6510.060HP, 7010.060HP, 7110.010HP, 7110.012HP, 7110.014HP, 7110.016HP, 7110.018HP, 7110.023HP, 7110.025HP, 7110.027HP, 7110.029HP, 7110.031HP, 7110.035HP, 7110.040HP, 7110.050HP, 7110.060HP, 7110.080HP, 7210.040HP, 7210.060HP, 7710.023HP, 7710.029HP, 0120.023HP, 0220.023HP, 0320.023HP, 0420.010HP, 0420.012HP, 0420.023HP, 0620.023HP, 0720.023HP, 0820.023HP, 0920.023HP, 1220.016HP, 1520.014HP, 1620.014HP, 1720.023HP, 1820.023HP, 3520.012HP, 5120.060HP, 5220.060HP, 5320.060HP, 5420.060HP, 5520.060HP, 5620.045HP, 5720.040HP, 5820.060HP, 6120.040HP, 6220.040HP, 6320.060HP, 6420.031HP, 7020.060HP, 7120.023HP, 7220.060HP, 7720.014HP, 7720.023HP, 7720.029HP, 0124.023HP, 1124.023HP, 1924.023HP, 2024.023HP, 2124.023HP, 2224.023HP, 5424.060HP, 6924.040HP, 7224.040HP, 7724.023HP, 1324.008HP, 1324.009HP, 1324.010HP, 0725.023HP, 0825.023HP, 1225.016HP, 1325.008HP, 1425.014HP, 1725.023HP, 6925.040HP, 7225.060HP, 0726.023HP, 0826.023HP, 1226.016HP, 1726.023HP, 6926.040HP, 0727.023HP, 0827.023HP, 1727.023HP, 6927.040HP, 7227.040HP, 7227.060HP, 0130.023HP, 0230.023HP, 0430.023HP, 0630.023HP, 0730.023HP, 0830.023HP, 0930.023HP, 1030.023HP, 1130.023HP, 1230.016HP, 1430.014HP, 1730.023HP, 1830.023HP, 5630.045HP, 5730.040HP, 5730.045HP, 7230.023HP, 7230.040HP, 7730.014HP, 7730.023HP, 7730.029HP, 0730.023HP, 1130.023HP, 0830.023HP, 1730.023HP, 0131.023HP, 0231.023HP, 0431.023HP, 0931.023HP, 1131.023HP, 0140.023HP, 0240.023HP, 0440.023HP, 0840.023HP, 5740.045HP, 0441.023HP, 1741.023HP, 5741.045HP, 5150.060HP, 5250.060HP, 5350.060HP, 5450.060HP, 5550.060HP, 5650.045HP, 5850.060HP, 6050.070HP, 7050.060HP, 5251.060HP, 5451.060HP, 5651.045HP, 5455.060HP, 5855.060HP, 6055.070HP, 0160.023HP, 0260.023HP, 0460.023HP, 1360.008HP, 1360.009HP, 1360.010HP, 1460.016HP, 5760.045HP, 5453.060HP, 6953.040HP, 7053.060HP, 1370.008HP, 1370.009HP, 1370.010HP, 5170.060HP, 5270.060HP, 5370.060HP, 5470.060HP, 5570.060HP, 5670.045HP, 5770.040HP, 5870.060HP, 5970.060HP, 6370.060HP,	Edenta Etablissement, Liechtenstein	Edenta Etablissement, Liechtenstein ; Edenta AG, Switzerland	Công ty TNHH Y tế Hoàn Mỹ	128 Hồ Văn Huê, Phường 9, Quận Phú Nhuận, TP.Hồ Chí Minh

6470.031HP, 6570.060HP, 7070.060HP, 7170.027HP, 7170.031HP, 7170.040HP, 7170.050HP, 7170.060HP, 7270.040HP, 7270.060HP, 0175.023HP, 5275.060HP, 5775.045HP, 6075.070HP, 7275.060HP, 7775.040HP, 5180.060HP, 5280.060HP, 5380.060HP, 5480.060HP, 5580.060HP, 5680.045HP, 5880.060HP, 5485.060HP, 5885.060HP, 6085.070HP, 5490.060HP, L0420.023HP, L5620.045HP, L0110.023HP, L5610.045HP, L5410.060HP, L6055.070HP, 513.014HP, 515.023HP, C514.023HP, C515.023HP, C108.104.060)

TC Cutter VOLCANO (DLC-0110.023HP, DLC-0210.023HP, DLC-0410.023HP, DLC-0610.023HP, DLC-1110.023HP, DLC-1210.016HP, DLC-1310.010HP, DLC-1610.014HP, DLC-5610.045HP, DLC-5710.040HP, DLC-5510.060HP, DLC-5210.060HP, DLC-5310.060HP, DLC-5410.060HP, DLC-7210.060HP, DLC-0120.023HP, DLC-0220.023HP, DLC-0420.023HP, DLC-1220.016HP, DLC-1620.014HP, DLC-5620.045HP, DLC-5720.040HP, DLC-5420.060HP, DLC-7220.060HP, DLC-1324.010HP, DLC-5424.060HP, DLC-6924.040HP, DLC-5450.060HP, DLC-5650.045HP)

CAD/CAM Cutter (202D.6.15.010, 202DA.6.15.010, 202D.6.20.020, 202DA.6.20.020, 202D.3.15.010, 202D.3.20.020, 202DR.3.16.010, 202DR.3.20.020, 202DR.3.20.025, 202.6.12.010, 202R.3.06.006, 202R.3.07.007, 202R.3.12.007, 202R.3.16.010, 202R.3.20.020, 202R.3.20.025, 202C.3.15.010, 202C.3.20.020, 202.3.15.010, 201.6.15.010, 201.3.12.010, 201.3.12.020, 201.3.16.010, 201.3.20.020, 201A.6.15.010, 201R.3.16.010, 201R.3.16.020, 102.3.15.010, 202B.6.15.010, 202BA.6.15.010, 202B.6.20.020, 202B.3.15.010, 202BR.3.16.010, 203BR.3.16.020, 202R.3S.07.007, 202R.3S.16.010, 202R.3S.20.025, 202R.3.15.010, 202R.3.05.006, 202R.3.16.006, 203R.3.16.020, 203R.3.16.030, 202.6.15.010, 202A.6.15.010, 202.6.20.020, 202.3.10.010, 202.3.14.010, 202.3.15.013, 202.3.15.015, 202.3.15.020, 202.3.08.007, 202.3.10.007, 202.3.18.010, 202.3.20.010, 202.3.20.020, 202R.3.02.006, 202R.3.08.010, 202R.3.12.020, N1.R2C.01, N1.R2C.02, N1.R2C.03, N1.R2C.04, N1.R4B.10, N1.R4B.09, N1.G.05, N1.G.06, N1.G.07, N1.G.08, N1.R2D.19, N1.R2D.20, N1.R2D.21, N1.R2D.22, N1.K3.14, N1.S.15, N1.R1.13, N1.T3.11, N1.R2.12, N1.R1.13)

2	Đĩa cắt răng giả	Diamond Disc (327.514.080, 327.514.100, 366.504.220HP, 367.504.220HP, 317.514.220HP, 317.524.220HP, 350.514.190HP, 350.524.190HP, 350.514.220HP, 350.524.220HP, 351.514.220HP, 351.524.220HP, 353.504.220HP, 353.514.220HP, 353.524.220HP, 355.504.190HP, 355.504.220HP, 355.514.160HP, 355.514.190HP, 355.514.220HP, 355.524.190HP, 355.524.220HP, 356.514.190HP, 356.514.220HP, 357.514.190HP, 357.514.220HP, 358.514.190HP, 358.524.190HP, 358.514.220HP, 358.524.220HP, 361.514.080HP, 361.514.100HP, 363.514.100HP, 393.514.220HP, 396.514.220HP, 400.514.220HP, 400.514.190HP, 405.514.220HP, 405.524.220HP, 605.514.220HP, 605.524.220HP, 705.514.190HP, 705.514.220HP, 321.514.190HP, 321.524.190HP, 321.514.220HP, 321.524.220HP, 335.524.220HP, 345.514.190HP, 345.514.220HP, 345.524.220HP, 365.524.300HP, 365.524.450HP, 378.524.450HP, 505.504.160HP, 505.504.190HP, 505.504.220HP, 505.514.190HP, 505.514.220HP, 362.524.080HP, 362.524.100HP, 354.524.220HP)	Edenta Etablissement, Liechtenstein	Edenta Etablissement, Liechtenstein ; Edenta AG, Switzerland	Công ty TNHH Y tế Hoàn Mỹ	128 Hồ Văn Huê, Phường 9, Quận Phú Nhuận, TP.Hồ Chí Minh
---	---------------------	--	---	--	---------------------------------	--